

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 29 & ~~28~~ Mer.

147

11

Corner common to Sections

30 and 1

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1
—
4

BT

Species _____

Diameter 6

Bearing ~~not confirmed~~ only BT

Distance 11 6 11

Do you believe this to be a genuine Land Office Corner? _____

If not, why? ~~No. Seem to be~~

~~a survey 16 years ago~~

EB Ste...


Signature.

2-8-29

Date.

F R

Title.



9-3027 (Make sketch of topography near corner.)

Metal Location Poster is on a *Corner* tree *6* inches diameter, on the *SE* side of from which this Corner bears *5 30 E* *20 feet* chains distant. Give any further facts which will aid in finding this Corner again.

*Marking base corners
 before about half done
 on open corner
 on open corner*