

U. S. Department of Agriculture
FOREST SERVICE

E-4

----- NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 46 R. 30-8 Mer.

E 1/4 Corner common to Sections
-----, -----, 6, and 7-----

Corner consists of a ----- (not) in place
State condition -----

Dimensions above ground ----- inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>E 1/2</u>
<u>S-6</u>

<u>E 1/2</u>
<u>S-7</u>

--

--

<u>B7</u>

<u>B7</u>

--

--

Species cedar -----

Diameter 6" 3" -----

Bearing W 7° N S 55° W -----

Distance 12.2 2.6 -----

Do you believe this to be a genuine Land Office Corner? -----

If not, why? -----

(Signature)

(Date)

(Title)

E-4

1-3

Corner again.

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. R. Mer. E-4