

U. S. Department of Agriculture  
FOREST SERVICE

E-5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146N R. 30W 5 Mer.

Sec.

Corner common to Sections

5, 6, 7, and 8

Corner consists of a Brass Cap in cement in place


State condition Good

Dimensions above ground 4" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 146N  
R. 30W  
S. 6

T. 146N  
R. 30W  
S. 5

T. 146N  
R. 30W  
S. 8

T. 146N  
R. 30W  
S. 7

BT

BT

BT

BT

Species Birch Ash W. Oak W. Oak

Diameter 6" 6" 10" 14"

Bearing S 87° N 77° E S 64° E S 83° W.

Distance 26 lk. 79 lk. 90 lk.

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

H C Norman  
(Signature)

7/20/37  
(Date)

(Title)

E-5

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Pester is on a

