

Form 974-9--Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

J-7

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 146 R. 30 5th Mer.

4th Corner common to Sections
9, and 17

Corner consists of a St. L. O. Corp. (not) in place
State condition Good

Dimensions above ground 5 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>BT</u>			

Species W.P. 22

Diameter 3'

Bearing N 58° E

Distance 90 d

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

W. J. ...
(Signature)

4/6/35

U. S. DEPARTMENT OF AGRICULTURE

FOREST SERVICE

INVESTIGATION REPORT

COMMISSION OF THE INTERIOR

UNITED STATES DEPARTMENT OF AGRICULTURE

FOREST SERVICE

INVESTIGATION REPORT

UNITED STATES DEPARTMENT OF AGRICULTURE

Corner again

Give any further facts which will aid in finding this

chain distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>
<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>
<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>
<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>

U. S. Department of Agriculture
FOREST SERVICE

J-7

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 46 R. 30 Mer. 5

1/4 Corner common to Sections 8, and 17



Corner consists of a Bronze top (not) in place
State condition good

Dimensions above ground 5 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species White Pine

Diameter 3

Bearing N 53° E

Distance 70

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

(Signature)

(Date)

(Title)

J-7

U. S. Department of Agriculture
FOREST SERVICE

P
5
/36

J-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 30 5th Mer.

4th Corner common to Sections
8, and 17


Corner consists of a 2x2 (not) in place
State condition Good

Dimensions above ground 2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species W. Pine

Diameter 3"

Bearing N 53 E

Distance .90 ch

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____


Franklin Wing
(Signature)

4/6/35
(Date)

(Title)

J-7

Metal Location Poster is on a
 tree inches diameter, on the
 side of
 from which this Corner bears
 chains distant.
 Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)

T. R. Mer.

U-7