

U. S. Department of Agriculture
FOREST SERVICE

E-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 30 Mer.

Section (1/4) Corner common to Sections
8, and 53

Corner consists of a 580 (not) in place



State condition in

Dimensions above ground ~~Underground~~ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Tom N.P.Diameter 10" 18"Bearing S NDistance 75' 150'

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

M. J. Murphy
(Signature)12/5/24
(Date)

(Title)

E-7

5.1

There are no magnetic fields
marked about a distance of
1/2 mile N. of corner

Corner again.

Give any further facts which will aid in finding this


150' chains distant.

from which this Corner bears N

side of road.

tree 1 1/2 inches diameter, on the N. 27.5

Metal Location Poster is on a Norway Pine



(Make sketch of topography near Corner)

T. J. R. 3 Mer. E-7