

T-9
Posted T-9

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146N. R. 30W. 5th Mer.

Quarter Corner common to Sections

....., 28, and 29.....

Corner consists of a Brass Capped Pipe (not) in place


State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species N. Pine N. Pine

Diameter 1 1/2" 7"

Bearing N. 19° 30' W. S 29° 45' E

Distance 35 7 1/4

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

J. A. Gjelhaug

(Signature)

10/10/34

(Date)

Teck Eng

(Title)

Corner again.

Give any further facts which will aid in finding this


004 chains distant.

from which this Corner bears North

side of Tree

tree .5" inches diameter, on the North

Metal Location Poster is on a R Oak



(Make sketch of topography near Corner)

T. 196N. R. 30W

529 Mer.

79