

U. S. Department of Agriculture  
FOREST SERVICE

T-13

Posted

Chippewa NATIONAL FOREST

## CORNERS OF THE PUBLIC SURVEY

T. 146N. R. 30W S<sup>14</sup> Mer.

Quarter Corner common to Sections

27, and 28

Corner consists of a Brass Caped Pipe (not) in place

State condition Good

Dimensions above ground 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION


N W S E


NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S 28
----------------

1/4 S 27
----------------

--

--

BT
----

BT
----

--

--

Species J. Pine J. Pine

Diameter 8" 8"

Bearing S59°45'W S54°30'E

Distance 291 690 1/2

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

J. A. Grelhaug

(Signature)

Tech. Eng.

(Title)


2/27/39  
(Date)

T-13

Corner out in open Swamp  
4 ft. oak post close to cor.

Corner again.

Metal Location Poster is on a tree ..... inches diameter, on the side of ..... from which this Corner bears ..... chains distant. Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T-13

T 146N. R. 30W. 5th Mer.