

U. S. Department of Agriculture
FOREST SERVICE

A-14
P
9
A-16 34

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 30 Mer. 52

E 1/2 Corner common to Sections
2-146-30, 434 and 147-30

Corner consists of a Wood Stake (not) in place
State condition Good

Dimensions above ground 48 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

4
14
S-3

--

--

--

BA

--

--

--

Species J Pine

Diameter 10"

Bearing NE

Distance 44 Ch

Do you believe this to be a genuine Land Office Corner? ye

If not, why? _____


Wing
(Signature)

4/22/35
(Date)

(Title)

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
OFFICE OF THE SURVEYOR GENERAL
DENVER, COLORADO

Corner again.
Give any further facts which will aid in finding this
off chains distant.
From which this Corner bears
side of
tree 10 inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

A-16
Mer
T. 146-14730