

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

V-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 N R. 80W 5th Mer.  
Quarter Corner common to Sections

26, and 35  
Corner consists of a metal cap (not) in place  
State condition good

Dimensions above ground 5 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION DIAGONAL POSITION

<b>26</b>		<b>35</b>	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

$\frac{1}{4}$   
S. 26

$\frac{1}{4}$   
S. 35

B. t.

Species J. P. J. P.

Diameter 8" 4"

Bearing NNE S7W

Distance 85 lbs 64 lbs

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Harold Hennes  
(Signature)

Jan. 14, 1937  
(Date)

(Title) V-19

