

U. S. Department of Agriculture
FOREST SERVICE

T-19

-----Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146N R. 30 W 5th Mer.

Quarter ----- Corner common to Sections

-----, -----, and 26

Corner consists of a metal cap (not) in place

State condition good

Dimensions above ground 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

26	26	26	26
----	----	----	----

N W S E

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

C 1/4 S.26			
B.T.			

Species J.P. -----

Diameter 6" -----

Bearing S77E -----

Distance 59 lks -----

Do you believe this to be a genuine Land Office Corner? **yes**

If not, why? -----

Harold Hennes

(Signature)

Jan 12, 1937

(Date)

(Title)

T-19

FI-1

SECTIONAL MAP

CONTOUR MAP

Scale 1:50,000

Sheet No. 1034-B

Sectional Map

Contour Map

Corner again.

Give any further facts which will aid in finding this


to the corner district

from which this corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



Section of topography near corner

T-19

T. 100 R. 20N Mer.