

U. S. Department of Agriculture
FOREST SERVICE

N-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 30 5th Mer.

Corner common to Sections 14, and 23

Corner consists of a *St. L. O.* (not) in place

State condition *Good*

Dimensions above ground _____ f. inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4
S-14

1/4
S-23

BT

B7

--

--

Species *R. Oak* *Aspen*

Diameter *4"* *5"*

Bearing *N 50 W* *S 40 E*

Distance *11 ch* *38 ch*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Murphy
(Signature)

5/14/35
(Date)

(Title)

N-19

U. S. Department of Agriculture
FOREST SERVICE

N-19

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. _____ R. _____ Mer. _____

Corner common to Sections _____, _____, and _____


Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species ROCK _____

Diameter 4" _____

Bearing N 80° E _____

Distance 11.5 _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

5/11/1918
(Date)

M. F. [Signature]
(Signature)
(Title)

N-19

