

U. S. Department of Agriculture
FOREST SERVICE

J-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 30 S. Ed Mer.

.....¹⁴ Corner common to Sections
.....,¹⁴, and¹⁴.....

Corner consists of a 2 1/2" cap (not) in place
State condition Good

Dimensions above ground¹² inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>B 7</u>			

Species T&D Spruce

Diameter 2" 3"

Bearing S 10° W N 5° W

Distance .09' .40'

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Murphy
(Signature)


5/6/25
(Date)

J-19

[Faint, mostly illegible text at the top of the page, possibly bleed-through from the reverse side.]

Corner again.

Give any further facts which will aid in finding this
chains distant
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 116 R. 30
J-19
M.T.