

U. S. Department of Agriculture
FOREST SERVICE

V-21

~~Chippewa~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 N R. 30 W S. 4 Mer.

Section Corner common to Sections

25, 26, 27, and 28

Corner consists of a Metal Cap (not) in place

State condition Surrounded with Cement

Dimensions above ground 8" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

26	26	26	26
NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

11.25 120° S. 26			
2.7			

Species J. Pine

Diameter 8"

Bearing S 80° W

Distance 118 lbs.

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

Harold Hanson

Jan 5, 1906

(Signature)

(Date)

(Title)

V-21

V-51

Give any further facts which will aid in finding this

Corner again.


1. ~~From~~ distant.

from which this Corner bears

side of

tree 3 inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 100 R. 100 Mer.