

U. S. Department of Agriculture
FOREST SERVICE

T-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 N R. 30W 5th Mer.

Quarter Corner common to Sections

25, and 26

Corner consists of a metal cap (not) in place

State condition good

Dimensions above ground 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

26			25

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4		1/4	
S.25		S.26	
B.T.		B.T.	

Species J. Pine N. Pine

Diameter 9" 16"

Bearing S71E S81W

Distance 9 lks 3 ch.

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Harold Hennes

(Signature)

Jan. 12, 1937

(Date)

(Title)

T-21

13-T

CORNER OF THE PUBLIC SURVEY


Give any further facts which will aid in finding this

chain distant

from which this Corner bears

tree 20 inches diameter, on the

Metal Location Poster is on a



Kind's standard topography near Corner

7-21