

U. S. Department of Agriculture
FOREST SERVICE

posted
N-21

CHIPPEWA NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. 146 R. 30 5 Mer.

SECTION Corner common to Sections
13, 14, 23, and 24

Corner consists of a No Post (not) in place
State condition _____

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION **DIAGONAL POSITION**



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		T146 R30 S24	T146 R30 S13
		BT	DT

Species	<u>JACUPINE</u>	<u>JACUPINE</u>	<u>JACUPINE</u>
Diameter		<u>18</u>	<u>16</u>
Bearing	<u>S65°E</u>	<u>S50°E</u>	<u>N25°E</u>
Distance	<u>27ft</u>	<u>30ft</u>	<u>25ft</u>

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Lester B. Mawson

2-13-34
(Date)

(Signature)
ESTIMATOR
(Title)

N-21

E & W NYS

LINE CUT BY FURNACE

Corner again.

Give any further facts which will aid in finding this

chains distant.

27 FT


from which this Corner bears N 65° W

N 65° W

side of TREE

tree 10 inches diameter, on the WEST

Metal Location Poster is on a JACK PINE



(Make sketch of topography near Corner)

N-21

Mer

R. 30

T. 146