

U. S. Department of Agriculture
FOREST SERVICE

T-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 28-30 5th Mer.

1/4 Corner common to Sections

, 25, and 30

Corner consists of a Brass Cap (not) in place

State condition Good

Dimensions above ground 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	25		30
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

B.T.	1/4 S. 30		
	B.T.		

Species Oak Oak

Diameter 2 1/4 2 1/8"

Bearing S. 92.5 W. S. 13° E.

Distance 38.5 lks. 79 lks.

Do you believe this to be a genuine Land Office Corner?

If not, why? _____

Harold Haines

(Signature)

Apr. 15, 1937

(Date)

(Title)

T-25

1-25

COMPOSITE OF PHOTOGRAPHS

Corner again.

Give any further facts which will aid in finding this


obtain distant.

from which this Corner bears 5.92.5 W.

side of Tree

tree 2 inches diameter, on the North east

Metal Location Poster is on an



(Make sketch of topography near Corner)

T-25

T. 196 R. 27+30 Mer. 5.74