

U. S. Department of Agriculture
FOREST SERVICE

T-U-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 140 N R. 30W 6th Mer.

TR 42-AP 4

Corner common to Sections

26

, and

Corner consists of a metal cap in place

State condition good

Dimensions above ground 5 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

			26
--	--	--	----

N W S E

26	26		
----	----	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

--	--	--	--

no bearing trees

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

Harold Hennes

(Signature)

Jan. 14, 1937

(Date)

(Title)

T-U-19

7-0-19

Map of topography near Corner

Corner again.

Tap paper house and out building
5 ch. North and 1.5 chain west

Give any further facts which will aid in finding this


chain distant

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

7-0-19

T. 248 N. R. 30W. 5th Mer.