

U. S. Department of Agriculture

FOREST SERVICE

G-1 G-1

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144⁶ R. 31-32 Mer.

Y4

Corner common to Sections

7, and 12

Corner consists of a 1/2 100 Cap (not) in place



State condition Good

Dimensions above ground 10" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species ASPEN ASPEN

Diameter 14" 9"

Bearing W 21° N 45° E

Distance 126 506

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

M. S. Murphy

4/11/35 (Date)

G-1 G-1

U. S. Department of Agriculture

FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

Corner located to the north of the corner of the public survey

Corner again

Give any further facts which will aid in finding this

12 chains distant


from which this corner bears

E. 1/2 mile

6 inches diameter, on the

N.E.

Metal Location Poster is on a



(Make sketch of topography near corner)