

U. S. Department of Agriculture
FOREST SERVICE

P 5
135
A19

Chippewa NATIONAL FOREST A-19

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 31 5th Mer.

Corner common to Sections 2-146-31, and 35-147-31

Corner consists of a M. L. O. Yard (not) in place
State condition

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 146 R. 31 Sec 2	T. 147 R. 31 Sec 33		
BT	BT		

Species N. Pine R. Oak

Diameter 12" 11"

Bearing S. 55° W N. 75° E

Distance 27 ch 123 ch

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Murphy
(Signature)

4/8/35
(Date)

U. S. Department of Agriculture

FOREST SERVICE

NATIONAL FOREST

CORNER OF THE PUBLIC SURVEY

1. This corner is located on the _____

_____ of the _____

_____ of the _____

_____ of the _____

_____ of the _____

_____ of the _____

_____ of the _____

_____ of the _____

_____ of the _____

_____ of the _____

_____ of the _____

_____ of the _____

_____ of the _____

_____ of the _____

_____ of the _____

_____ of the _____

_____ of the _____

_____ of the _____

_____ of the _____

_____ of the _____

_____ of the _____

_____ of the _____

_____ of the _____


_____ of the _____

_____ of the _____

_____ of the _____

_____ of the _____

_____ of the _____



(Make sketch of topography near Corner)

A-19

Mer

117-31 B. 3/1