

U. S. Department of Agriculture
FOREST SERVICE

T-U-17 FULL

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 146 R. 31 5th Mer.

Meander Corner common to Sections
26, and 27.

Corner consists of a Brass capped iron (not) in place
State condition good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

M.R.
S. 27

M.C.
S. 26

B.T.

B.T.

Species Ash Ash

Diameter 7" 7"

Bearing N 48° W S 25° 45' E

Distance 4 24 1/2

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Carl Steadland

3/19/35
(Date)

Jr. East
(Title)

T-U-17

U. S. Department of Agriculture

CORNERS OF THE PUBLIC SURVEY

NATIONAL FOREST

7-10-17

T. R. 181

Corner consists of a ...

Corner again.

State condition

Give any further facts which will aid in finding this

Distance from ...

from which this corner bears

side of ...

tree 7 inches diameter, on the SE

Metal Location Poster is on a

N W S E NW SW NE SE

is located

is located

Sketch map of bearing trees (or rocks) in proper order

Fill blanks below giving bearings from corner to trees and

Distances in feet.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine land office corner?

Not with ...

Sec 16

Mc. Cass Lake

(Date sketch of topography near corner)