

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

~~A-25~~  
 4-11

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. <sup>147</sup>147 R. <sup>26</sup>25 5th Mer.

Section \_\_\_\_\_ Corner common to Sections  
 1, 6, 31, and 36

Corner consists of a Cedar post (not) in place  
 State condition fair

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

Sec 36 T 148 26	Sec 31 T 148 25	Sec 1 T 147 26	Sec 6 T 147 25
--------------------------	--------------------------	-------------------------	-------------------------

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

			BT

Species \_\_\_\_\_ *Tam. Stump*  
 Diameter \_\_\_\_\_ *10"*  
 Bearing \_\_\_\_\_ *S 12° E From Coy Rod post*  
 Distance \_\_\_\_\_ *18 Lks*

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? *No*

*No notes covering this cor. in orig. field notes.*

*Virgil R. Smith*

(Signature)

*6-4-56*

(Date)

*G. D. H.*

(Title)

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this


*Approx 10.75 chains distant.*

from which this Corner bears *N 80 W*

side of *Tree*

tree 1.0" inches diameter, on the *EAST*

Metal Location Poster is on a *Birch*



(Make sketch of topography near Corner)

*T. 147-2542*  
*T. 148-2542*  
*N. 57* Mer.