

U. S. Department of Agriculture  
FOREST SERVICE

J-6

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 197N R. 25W 57th Mer.

W. 1/16 Corner common to Sections  
8, and 17



Corner consists of a None (not) in place  
State condition

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Cedar

Diameter 1 1/4"

Bearing N90E

Distance 57/1ks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Records show it was set by County Surveyor

Harold Hamalain

(Signature)


Enrolled

(Title)

2/17/40  
(Date)

Corner again.  
Post should set in E of road

Give any further facts which will aid in finding this  
chains distant.  
from which this Corner bears  
side of  
tree inches diameter, on the  
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 197N R. 25W Mer. 27 1/2

U. S. Department of Agriculture

FOREST SERVICE

J6

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 197N R. 25W 5th Mer.

W. 1/16 Corner common to Sections

8, and 17

Corner consists of a None (not) a place


State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Cedar

Diameter 19"

Bearing N 90 E

Distance 511ks.

Do you believe this to be a genuine Land Office Corner? No

If not, why? Records show it was set by County Surveyor

H. Hamalainen

(Signature)


Enrollee

(Title)

2/7/90

(Date)

(Make sketch of topography near Corner)



T. 197N R. 25W. 5th Mer.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.

Post should set in E of road.

U. S. Department of Agriculture  
FOREST SERVICE

J-6

JB

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 25W 5th Mer.

W. 1/16 Corner common to Sections

8, and 17

Corner consists of a None (not) a place

State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Cedar

Diameter 14"

Bearing N90E

Distance 511ks.

Do you believe this to be a genuine Land Office Corner? No

If not, why? Records show it was set by County Surveyor.

H. Hamalainen

(Signature)

2/7/90

(Date)

Inspector

(Title)

Post show section E of road.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 197N R. 25W 5th Mer.