

U. S. Department of Agriculture
FOREST SERVICE

K7

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. *197N.* R. *25W* *5th* Mer.

C.N. 116 Corner common to Sections
16, *17*, and *17*

Corner consists of a *None* (not) in place



State condition

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *E/m* *K/m*

Diameter *12"* *12"*

Bearing *588°E* *560°N.*

Distance *201k2* *281k3.*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? *Records show it was set by County Surveyor*

H. Hamalainen

(Signature)


2/6/40

(Date)

Emble

(Title)

Metal Location Poster is on a
 tree inches diameter, on the
 side of
 from which this Corner bears
 chains distant.
 Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)

T. 197N R. 25W
 Mer. 574

U. S. Department of Agriculture
FOREST SERVICE

K-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 25W 5th Mer.

C.N 116 Corner common to Sections

.....,, and 17.....

Corner consists of a None (not) in place

State condition

Dimensions above ground inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Elm Elm

Diameter 12" 12"

Bearing S88°E S60°W

Distance 201ks 201ks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Records show it was set by

County Surveyor

H. Hanselman

(Signature)

Enroller

(Title)

3/6/40

(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

	Sec. 17		
		Sec. 17	
	Sec. 17		

(Make sketch of topography near Corner)

T. 197N R. 25W Mer. 5th

U. S. Department of Agriculture
FOREST SERVICE

K-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 177N R. 25W 5th Mer.

C.N. 116 Corner common to Sections

and 17

Corner consists of a None (not) in place


State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Elm Elm

Diameter 12" 12"

Bearing 300E 360N

Distance 201ks 201ks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Records show it was

set by County Surveyor

Harold Hamalainen

(Signature)

Emalle

(Title)


2/16/40

(Date)

1

Corner again.

Give any further facts which will aid in finding this
 ----- chains distant.
 ----- from which this Corner bears
 ----- side of
 ----- tree ----- inches diameter, on the
 ----- Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 197N. R. 25W. 5th Mer.