

U. S. Department of Agriculture

FOREST SERVICE

*posted*  
*29*

*Copper*

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *47* N. R. *1* Mer.

Corner common to Sections *27*, *33*, and

Corner consists of a (not) in place State condition

Dimensions above ground inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N . W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>120</i>			
<i>120</i>			

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why?

*11-2-18* (Date) *[Signature]* (Signature) *[Title]* (Title)

Corner again.  
Rocky hill  
UT sec. 10 11 12

Give any further facts which will aid in finding this chains distant.

from which this Corner bears  
side of road  
tree 4 inches diameter, on the E side  
Metal Location Poster is on a

<input checked="" type="checkbox"/> 2. Bitter Sec. 33	B1	Sec. 32	Road
Sec. 33		Sec. 34	

(Make sketch of topography near Corner)