

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

*posted*  
X9

*Clayton* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *14* R. *15* Mer.

Corner common to Sections *7*, *27*, and *20*


Corner consists of a \_\_\_\_\_ (not) in place  
State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *112* \_\_\_\_\_

Diameter *1 1/2"* \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

\_\_\_\_\_

*L. H. ...*

(Signature)


*11-27-33*

(Date)

*...*

(Title)

Metal Location Poster is on a *4* inches diameter, on the *West* side of *road* from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147 R. 25 Mer.