

U. S. Department of Agriculture
FOREST SERVICE

K9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 25 W 5th Mer.

N. 1/16 Corner common to Sections

16, and 17

Corner consists of a 3" excised Post (not) in place



State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Elm Elm

Diameter 8" 10"

Bearing S 97° E N 49° W

Distance 23 lks 52 lks

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Records show it was set by

County Surveyor

H. Hamalainen

(Signature)

Emallee


(Title)

2/6/40

(Date)

(Make sketch of topography near Corner)

T. 192N R. 25W S7 Mer.



Metal Location Poster is on a tree _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.

U. S. Department of Agriculture
FOREST SERVICE

K-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 197N R. 25W 5th Mer.

N. 1/16 Corner common to Sections

16, and 17

Corner consists of a 3" Scrubbed Post (not) in place


State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Elm Elm

Diameter 8" 10"

Bearing S 97° E N 90° W

Distance 23 lks 52 lks

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Records show it was set by

County Surveyor

H. Hamalainen

(Signature)


Enrollee

(Title)

2/6/10

(Date)

(Make sketch of topography near Corner)



T. 197N. R. 26W. 574 Mer.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.

1

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

K⁹

CORNERS OF THE PUBLIC SURVEY

T. 197N R. 25W 5th Mer.
N 1/6 Corner common to sections

16, and 17

Corner consists of a 3 Scribed Post (one) in place



State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Elm Elm

Diameter 8" 10"

Bearing S97°E N99°W

Distance 231ks 521ks

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Records show it was set by County Surveyor

Harold Hamalainen

(Signature)


2/6/90

(Date)

Enroller

(Title)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 197N R. 25W 57h Mer.