

U. S. Department of Agriculture
FOREST SERVICE

E12

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *147N* R. *25W* *5th* Mer.

E 1/6 Corner common to Sections
4, and *9*

Corner consists of a *3" scribed Cedar Post (not)* in place



State condition *New*

Dimensions above ground *18* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *J. Pine*

Diameter *6"*

Bearing *N 8° E*

Distance *691ks*

Do you believe this to be a genuine Land Office Corner? *No*


If not, why? *Set by J. A. Bjelhave*

Arthur J. Johnson
(Signature)
Squad Foreman
(Title)

2/27/40
(Date)

(Make sketch of topography near Corner)

T. 197N R. 85W S. 5N Mer.



Metal Location Poster is on a *The B.T*

tree inches diameter, on the *North*

side of *Road*

from which this Corner bears *58°W*

.69 chains distant.

Give any further facts which will aid in finding this

Corner again.

U. S. Department of Agriculture

FOREST SERVICE

E-12

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 197N R. 25W 5th Mer.

E 1/16 Corner common to Sections

1, and 9

Corner consists of a 3" Scrubbed Cedar Post (not) in place


State condition New

Dimensions above ground 18 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species J. Pine

Diameter 6"

Bearing N 8° E

Distance 69 lks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Set by J. A. Gjelhaug


Arthur S. Johnson (Signature)

Special Foreman (Title)

2/27/90 (Date)

(Make sketch of topography near Corner)

T. 122N R. 25W 5th Mer.



Metal Location Poster is on a *7 1/2* B.T.

tree *1* inches diameter, on the *North*

side of *road*

from which this Corner bears *58° W*

69 chains distant.

Give any further facts which will aid in finding this

Corner again.

U. S. Department of Agriculture
FOREST SERVICE

E-12

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 197N R. 25W 5th Mer.

E 1/6 Corner common to Sections
4 and 9



Corner consists of a 3" scribed Cedar Post in place
State condition New

Dimensions above ground 7 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Ja Pine
Diameter 6"
Bearing N 8° E
Distance 69 lks

Do you believe this to be a genuine Land Office Corner? NO
If not, why? Set by J. A. Gjelhaug


Arthur J. Johnson
(Signature)

2/27/90
(Date)

Special Foreman
(Title)

(Make sketch of topography near Corner)

T. 127N R. 25W 5th Mer.



Metal Location Poster is on *the B.T.*

tree *inches diameter, on the North*

side of *Road*

from which this Corner bears *58° W*

691/3 chains distant.

Give any further facts which will aid in finding this

Corner again.