

U. S. Department of Agriculture

FOREST SERVICE

J13
posted

CHIPPANWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 23 5 Mer.

Corner common to Sections 9, 10, 15, and 16



Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Paul J. [Signature]

(Signature)

11-28-33

(Date)


[Signature]

(Title)

Corner section on the West side of
Town Road. corner in front
of house

Corner again.

Metal Location Poster is on a
tree inches diameter, on the
side of from which this Corner bears
chains distant.
Give any further facts which will aid in finding this
Corner again.



(Make sketch of topography near Corner)

T. 147 R. 25 Mer. 5