

U. S. Department of Agriculture

FOREST SERVICE

V-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 25 W 5th P Mer.

14 Corner common to Sections 27, and 34

Corner consists of a stake (~~not~~) in place

State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>14</u>		<u>14</u>	
<u>5</u>		<u>5</u>	
<u>27</u>		<u>34</u>	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? Co. Prop.

George H. Jennings  
(Signature)

11-4-35  
(Date)

J. H. Brown C. M.  
(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant

0.39

from which this Corner bears

S 15 SW

side of


pole

inches diameter, on the

S 1/2

Metal Location Poster is on a

for tele pole



(Make sketch of topography near Corner)

T. 147N R. 25W 5th P. Mer.