

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

21-18

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 25 W 5th Mer.

W 16 Corner common to Sections

14, 23, and

Corner consists of a wooden stake (not) in place

State condition Good

Dimensions above ground 3 ft. inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	W 1 16 5 15		W 1 16 5 23
--	-------------------------	--	-------------------------

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T147N
R25W
W 1/2 STA

T147N
R25W
W 1/2 23

Species Birch oak

Diameter 6" 4"

Bearing N26°E N66°W

Distance 67.7K 13.7K

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Donald Poole
 (Signature)

12-17-34
 (Date)

(Title)

1

Corner again.

Give any further facts which will aid in finding this

----- chains distant.

----- from which this Corner bears

----- side of

----- tree ----- inches diameter, on the

----- Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

N-18

~~Chippewa~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 25 W 5 Mer.

W 1/6 Corner common to Sections 14, and 23


Corner consists of a ~~wood stake~~ in place State condition 9 Road

Dimensions above ground 36 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch Birch

Diameter 6" 9"

Bearing N36 E N66 W

Distance 67' 131'

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Donald Cook

(Signature)

12-19-13

(Date)

(Title)

Metal Location Poster is on a tree _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant. Give any further facts which will aid in finding this Corner again.

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

Mer.

R.

T. 1777