

U. S. Department of Agriculture
FOREST SERVICE

B 21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *147* R. *25* *5th* Mer.*N 1/16* Corner common to Sections*23, + 24*, andCorner consists of a *iron monument* (not) in placeState condition *good.*

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species *J. Pine* *J. Pine*Diameter *18"* *9"*Bearing *S 13 1/2° E* *N 73 1/2° W*Distance *26.0* *29.5*Do you believe this to be a genuine Land Office Corner? *No*If not, why? *Set by Co. surveyor April 1934**by D. H. Wilson notes taken from*
Co. record book of survey.

(Signature)

4/23/37


(Date)

(Title)

Corner along Highway

Corner again.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147 R. 25 Mer. 5-24