

Form 874-B—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

4-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 25 W _____ 5 Mer.

_____ N 1/16 Corner common to Sections
 _____, _____, 1, and 2

Corner consists of a 4" cedar (~~not~~) in place
 State condition good

Dimensions above ground 36" _____ inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S		S
	2		1
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

			S
			1
			B.T.

Species _____ W. PINE
 Diameter _____ 40"
 Bearing _____ S 80 E
 Distance _____ 20 Li

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Ervin Meagher

(Signature)

9-19-35
 (Date)

Field Ass't
 (Title)

N 1/2 COR. 15 ON FENCE
LINE LAND LEVE
SECOND GROWTH ASPEN


Corner again.

Give any further facts which will aid in finding this

20 ft. chains distant.

from which this Corner bears
side of STUMP N 80 W

Metal Location Poster is on a
tree 40 inches diameter, on the N W
W. PINE STUMP



(Make sketch of topography near Corner)

T 142 N R 25 W 5 Mer.

Form 574-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 147N R. 25W 5 Mer.

N 1/16 Corner common to Sections
1, and 2

Corner consists of a 4" cedar (nat) in place

State condition good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S		S
	2		1
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

			S 1
			B.T

Species _____ W. PINE STUMP
 Diameter _____ 140"
 Bearing _____ S 80 E
 Distance _____ 20 Li 0

Do you believe this to be a genuine Land Office Corner? YES

If not, why? _____

Ervin Meagher

(Signature)

9-19-35

(Date)

Field Ass't

(Title)

N 1/2 COR. 15 ON FENCE
LINE, LAND LEVEL,
SECOND GRAMMITH ASPEN

Corner again.


Give any further facts which will aid in finding this

20 LI. chains distant.

from which this Corner bears N 80 W

side of STUMP

Metal Location Poster is on a W. PINE STUMP
tree 40" inches diameter, on the N W



(Make sketch of topography near Corner)

T. 17N R. 25W Mer. 5

Form 874-9 - Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

C-21

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 147N R. 25W 5 Mer.

14 Corner common to Sections
1, and 2

Corner consists of a 4" ash post in place
State condition good

Dimensions above ground 30" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S		S
	2		1
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

			S 1
			B.T

Species _____ B. spr
Diameter _____ 8"
Bearing _____ N33E
Distance _____ 11.6i
Do you believe this to be a genuine Land Office Corner? yes
If not, why? _____

Ervin Meagher

(Signature)

9-19-35
(Date)

Field Ass't
(Title)

CORNER IS ON FENCE LINE
MOTION AND HIDER SWAMP

Corner again.

Give any further facts which will aid in finding this


11.7! corners distant.

from which this Corner bears 533 W

side of tree

tree 8 inches diameter, on the S W

Metal Location Posters on a B. Spr.



(Make sketch of topography near Corner)

T. 142N R. 25W Mer. 5

U. S. Department of Agriculture
FOREST SERVICE

C-21

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 25 W 5 Mer.

1/4 Corner common to Sections
1, and 2

Corner consists of a 4" ash post (not) in place

State condition good

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S		S
	2		1
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

			S
			1
			B.T

Species _____ B. Spr

Diameter _____ 8"

Bearing _____ N33E

Distance _____ 11.1

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Ervin Meagher

(Signature)

9-19-35

(Date)

Field Ass't

(Title)

WILLOW AND ALDER SWAMP
COR. IS ON FENCE LINE

Corner again.

Give any further facts which will aid in finding this


corner distant.

11.7!
from which this Corner bears S53W

side of Tree

tree 8 inches diameter, on the S.W.

Metal Location Poster is on a B. S. P.



(Make sketch of topography near Corner)

T. 147N R. 25W Mer. 5