

U. S. Department of Agriculture
FOREST SERVICE

75

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 27 5th Mer.

Quarter Corner common to Sections
30, and 29

Corner consists of a Iron pipe (not) in place



State condition Good

Dimensions above ground 1" 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Ash Ash
Diameter 7" 10"
Bearing N71 1/2 W N53 E
Distance .11 .30

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Walter Haberle

(Signature)

Leader

2/18/40

(Date)

(Title)

110

Series of horizontal dashed lines for writing.

Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the

Metal Location Poster is on the berring trees

	Sec.		
	Sec.		
	Sec.	30	
	Sec.	29	

(Make sketch of topography near Corner)

Form 874-B—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

T-5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 27 5th Mer.

Quarter Corner common to Sections
 , 30 , and 29

Corner consists of a Iron pipe (not) in place



State condition good

Dimensions above ground 1"12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



BT

BT

--

--

Species Ash Ash

Diameter 7" 10"

Bearing N71 1/2 W N53 E

Distance .11 .30

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Walter Haberle

(Signature)

2/18/40

(Date)

Leader

(Title)

118

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

Chippewa NATIONAL FOREST

T-5

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 27 5th Mer. Quarter

Corner common to Sections 30, and 29

Corner consists of a Iron pipe (not) in place


State condition good

Dimensions above ground 1"12" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Ash Ash
 Diameter 7" 10"
 Bearing N71 $\frac{1}{2}$ W N53E
 Distance 11 30

Do you believe this to be a genuine Land Office Corner? Yes
 If not, why?

Walter Haberle


2/18/40
 (Date)

(Signature)
 Leader
 (Title)

Series of horizontal dashed lines for writing.

Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a
The bearing trees



(Make sketch of topography near Corner)