

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

65
Posted

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 147N R. R2W Mer.



4 Corner common to Sections
....., 7, and 8.....

Corner consists of a sat faced Jack Pine in place
State condition Good

Dimensions above ground 17" D.O.A. 72' high inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and
fill blanks below, giving bearings from Corner to Trees and
Distances in Links.



Species J.P. the witness tree is a snag
Diameter 13" 15' high
Bearing N 35° W
Distance 17

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

W. Danks
(Signature)


9/15/34
(Date)

Tech. Foreman
(Title)

located on rolling ground in scattered Jack Pine stand.

Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

6-5

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

1/4 Corner common to Sections 7, and 8

Corner consists of a Iron Pipe (not) in place



State condition just erected

Dimensions above ground 1 - 27 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species N.P. N.P.

Diameter 4" 10"

Bearing N 6 1/2 E S 60 1/2 W

Distance .26 .32

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

(Signature)

1936

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 197N R. 27W 6th Mer.

U. S. Department of Agriculture
FOREST SERVICE

G-5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14 N R. 27 W 5th Mer.

Corner common to Sections

Corner consists of a Iron Pipe (not) in place


State condition just set

Dimensions above ground 1-27 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species N.P. N.P.

Diameter 4" 10"

Bearing N 60° E S 60° W

Distance .26 .32

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

1936


(Signature)

(Date)

(Title)

Metal Location Poster is on a _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 149N R. 27W 6th Mer.

U. S. Department of Agriculture
FOREST SERVICE

G-5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 87W 57 1/2 Mer.



1/4 Corner common to Sections 2 and 8

Corner consists of a Iron Pipe in place
State condition OK

Dimensions above ground 1" - 27 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Found of Iron Pipe is located at the corner

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species N.P. N.P.

Diameter 4" 10"

Bearing N 60° W S 60° W

Distance 20 32

Do you believe this to be a genuine Land Office Corner?

If not, why? Yes


(Signature)

(Date)

(Title)

39

Corner again.
 Give any further facts which will aid in finding this
 chain distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 143N R. 21W Mer.