

U. S. Department of Agriculture  
FOREST SERVICE

27

CHIPPewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. <sup>148</sup>147 N. R. 27W 5th Mer.

N<sub>1</sub> Corner common to Sections

32, and 5

Corner consists of a wooden stake (500) in place

State condition Good

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

None			

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

None			

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No  
If not, why? Run by state, using transit -  
no bearing trees

J. M. Stephens  
(Signature)

Technical Foreman

3/2/35

(Date)

(Title)

U. S. DEPARTMENT OF THE INTERIOR

Geological Survey

WATER RESOURCES DIVISION

CORNER OF THE SECTION

Post on Dixon Lake Road

White post with location

Corner again.

Give any further facts which will aid in finding this


chain distant.

from which this Corner bears N 90° W

side of road

tree 3 inches diameter, on the East

Metal Location Poster is on a TAMARACK



(Make sketch of topography near Corner)

T. 147 N. R. 27 W. S. Mer.