

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

89

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.
Quarter

Corner common to Sections
20, and 21

Corner consists of a Brass cap on (not) in place
State condition good

Dimensions above ground 1"12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

T147N	R27W		
S20	S21		
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T147N R27W S20	S21		
BT	BT		

Species Ash Birch
Diameter 4" 6"
Bearing S88W N65E
Distance .46 .22

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Walter Haberle

(Signature)

2/12/40

Leader

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a The bearing trees



(Make sketch of topography near Corner)

T. 147N R. 27W 5th Mer.

U. S. Department of Agriculture

FOREST SERVICE

R 9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 27 5th Mer. Quarter

Corner common to Sections

20, and 21

Corner consists of Brass cap on pipe in place



State condition good

Dimensions above ground 1 1/2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Ash Birch

Diameter 4" 6"

Bearing S 88 W N 65 E

Distance .46 .22

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Walter Haberle

(Signature)

Leader

(Title)

2/12/40

(Date)

Corner again.

Give any further facts which will aid in finding the


chain distant.

from which this Corner bears

side of

tree. inches diameter, on the

Metal Location Poster is on the bearing trees



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

P-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY



T. 147N R. 27W 5th Mer.
Quarter

Corner common to Sections
20, and 21

Corner consists of Brass cap on pipe in place
State condition good

Dimensions above ground 1"12" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Ash Birch

Diameter 4" 6"

Bearing S88W N05E

Distance 446 .22

Do you believe this to be a genuine Land Office Corner? ...Yes


If not, why? _____

Walter Haberle

2/12/40
(Date)

(Signature)
Leader
(Title)

Metal Location Poster is on the bearing trees
 tree inches diameter, on the
 side of
 from which this Corner bears
 chains distant.
 Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

P. 9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 7 W 5th Mer.

Corner common to Sections

20, and 21

Corner consists of a Iron Pipe (not) in place



State condition Good

Dimensions above ground 1' - 27" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch Ash

Diameter 6 4

Bearing N65°E 588W

Distance 22 46

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

(Signature)

(Date)

(Title)

81

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 1st 7th R. 22nd S. 7th Mer.