

U. S. Department of Agriculture

FOREST SERVICE

J-11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N. R. 27 W. 5th Mer.

1/4 Corner common to Sections

9, and 16

Corner consists of a iron pipe (not) in place



State condition Just Erected

Dimensions above ground 1' - 28" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>5/16</u>	<u>59</u>		
<u>B.T</u>	<u>B.T</u>		

Species W.P. N.P.

Diameter 12" 4"

Bearing S 26 1/2° W N 64 3/4° W

Distance 1.04 35

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____


(Signature)

(Date)

(Title)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 14 N. R. 27 W. 5th Mer.

U. S. Department of Agriculture
FOREST SERVICE

*Copied
Posted
7/36.
J11*

----- NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 27 Mer. 5

----- Corner common to Sections

9, 16, -----, and -----

Corner consists of a no stake ----- (not) in place
State condition -----

Dimensions above ground ----- inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species -----

Diameter -----

Bearing -----

Distance -----

Do you believe this to be a genuine Land Office Corner? -----

If not, why? -----

(Signature) -----

(Date) -----


(Title) -----

Form No. 10-1-1916

CORNERS OF THE PUBLIC SURVEY

Corner again. 18" R. B. disk
 Corner consists of 18" disk (not in place)

Give any further facts which will aid in finding this
 corner distance
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a



(Make sketch of topography near Corner)

Form 574-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

J-11

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W Sth 5th Mer.

1/4 Corner common to Sections
9 and 16

Corner consists of 20 I P (not) in place



State condition

Dimensions above ground 1" 28 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>8 7/16</u>	<u>59</u>		
<u>BT</u>	<u>BT</u>		

Species W.P N.P

Diameter 1 1/2" 1 1/2"

Bearing S 20° W N 62° W

Distance 104' 35'

Do you believe this to be a genuine Land Office Corner?

If not, why?

[Handwritten Signature]

(Signature)


(Date)

(Title)

TAXON...
...
...

Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 142M R. 29W
Mer.