

U. S. Department of Agriculture
FOREST SERVICE

B11
Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5 Mer.

N 1/16 cor. s.c. 4 Corner common to Sections

N 1/4, N 1/2, S 1/4, and S 1/2 sec. 4

Corner consists of a wooden ~~(not)~~ in place

State condition Good

Dimensions above ground 36" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

NE	SW	SE	NW
NW	NE	NW	NE

N W S E

NW SW SE NE

Mound of None is located

Pits are located None

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

N		N	E

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? No Bearing trees


3/30/35

(Date)

John M. Stephens Jr.
(signature)

Richard L. Carraway
(Title)

Metal Location Poster is on a **Aspen** tree **8** inches diameter, on the **South** side of **Tree** from which this Corner bears **11** chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)