

U. S. Department of Agriculture
FOREST SERVICE

CHIPPewa NATIONAL FOREST

R-17

CORNERS OF THE PUBLIC SURVEY

T. 147 N. R. 27 W. 5th Mer.

Section Corner common to Sections

22, 23, 27, and 26

Corner consists of a Buzzsaw ^{FILE} in place


State condition good.

Dimensions above ground 18 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N. W. S. E.

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



N. W. S. W. S. E. _____

Species N. Pine N. Pine Windfall

Diameter 2 1/2 3 1/2 3 1/2

Bearing N. 37° W. S. 55° W. S. 53° E.

Distance .75 ch. .64 ch. .95 ch.

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Jerome R. Nomola
(Signature)

June 1, 1925
(Date)

J. J. [unclear]
(Title)

Faint, illegible text on lined paper, possibly bleed-through from the reverse side.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. W. R. 2700 S. 17. Mer.

U. S. Department of Agriculture
FOREST SERVICE

P
R17



CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 27 W 5th Mer.
section
22, 23, 27, and 26

Corner consists of a brass cap on pipe (not) in place
State condition good


Dimensions above ground 18 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species N pine N pine NP windfall
Diameter 24" 36" 48"
Bearing N 37° W S 55° W S 53° E
Distance 175 ch .64 ch. .95 ch.

Do you believe this to be a genuine Land Office Corner? Yes


If not, why? _____

J. J. ...
(Signature)
June 1, 1925
(Date)
(Title)

Blank lined area for notes or observations.

Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)