

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

*Copied
 Posted
 57
 36
 E-19*

----- NATIONAL FOREST -----

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 27 S. 5 Mer.

$\frac{1}{4}$ Corner common to Sections
2, 11, _____, and _____

Corner consists of a iron stakecenter of Max (not) in place
road State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

(Signature)

(Date)

(Title)

COMMISSIONERS OF THE BUREAU OF LAND MANAGEMENT
BUREAU OF LAND MANAGEMENT
WASHINGTON, D. C. 20250

Corner again
H T all out down

Give any further facts which will aid in finding this
chain distance
from which this Corner bears
side of
tree
inches diameter, on the
Metal Location Poster is on a

	Sec. II		Sec. II
		D. All. com.	
	Sec. II		Sec. II

(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

R
E 19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *147N* R. *27W* *5th* Mer.

1/4 Corner common to Sections *2*, and *11*



Corner consists of a *iron pipe* in place
State condition *just ERECTED*

Dimensions above ground *1" - 28"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION





N W S E NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *N.P.* *N.P.*

Diameter *1 1/2* *6*

Bearing *N 77 1/4 E 5 13/20*

Distance *46* *50*

Do you believe this to be a genuine Land Office Corner?

If not, why? *yes*

(Signature)

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 147N R. 27W 5th Mer.

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST **E-19**
CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th - Mer.

1/4 Corner common to Sections 2 and 11

Corner consists of a JE P (stone) in place



State condition JE P

Dimensions above ground 1 1/2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of stone is located at

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species NP NP

Diameter 1 1/2 6

Bearing N 77 1/2 E 54 3/4 W

Distance 46 50

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

(Signature)


(Date)

(Title)

Faint, illegible text at the top of the page, possibly bleed-through from the reverse side.

Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 142N R. 29W 574-Mer.

U. S. Department of Agriculture

FOREST SERVICE

E-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 117N R. 27W 5th Mer.

Corner common to Sections

2, and 11

Corner consists of a Iron Pipe (not) in place


State condition just Erected

Dimensions above ground 1"-2.8" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species N.P. N.P.

Diameter 1.5" 6"

Bearing N77 1/4 E S 5 13 1/2 W

Distance 46 50

Do you believe this to be a genuine Land Office Corner?

If not, why? yes


(Signature)

(Date)

(Title)

Metal Location Poster is on a tree _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 142N R. 27W 6-7h Mer.