

U. S. Department of Agriculture  
FOREST SERVICE

*P*  
*vrh*

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *147N* R. *27W* *5th* Mer.

*Section* Corner common to Sections  
*26, 25, 35, and 36*

Corner consists of a *Iron pipe* (not) in place  
State condition *new*

Dimensions above ground *23" by 3 1/2" hole* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<i>26</i>	<i>25</i>	
	<i>35</i>	<i>36</i>	


N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	<i>none</i>	<i>given</i>	

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_


(Signature)

(Date)

(Title)

Metal Location Poster is on a tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_ side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 142N R. 27W 5th Mer.

U. S. Department of Agriculture  
FOREST SERVICE

V-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

Section Corner common to Sections  
24, 25, 35, and 36

Corner consists of a Iron pipe (not) in place  
State condition new

Dimensions above ground 73' by 3 1/2' <sup>10' of iron</sup> inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	24	25	
35		36	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>None</u>	<u>None</u>	<u>None</u>	<u>None</u>

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_  
If not, why? \_\_\_\_\_


(Signature)

(Date)

(Title)

Metal Location Poster is on a tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_ side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147 N. R. 27 W. 5th Mer.

U. S. Department of Agriculture  
FOREST SERVICE



Chippewa NATIONAL FOREST V-21

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W Mer. Section 26, 25, 35, and 36

Corner consists of a 3" Iron pipe in place State condition 1927

Dimensions above ground 3" pipe 24 ft above, Sketch grooves, letters, figures, or notches, on proper face or edge.



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_ Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_ Diameter \_\_\_\_\_ Bearing \_\_\_\_\_ Distance \_\_\_\_\_


Do you believe this to be a genuine Land Office Corner? If not, why?

(Signature)

(Date) (Title)

25047

(Make sketch of topography near Corner)



Metal Location Poster is on a

tree inches diameter, on the

side of

from which this Corner bears

chains distant.

Give any further facts which will aid in finding this

Corner again.

COMMISSION OF THE PUBLIC LANDS