

U. S. Department of Agriculture
FOREST SERVICE

P
271

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

1/4

Corner common to Sections

14, and 13

Corner consists of a Iron Pipe (not) in place


State condition just erected

Dimensions above ground 1' - - - 28" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species SD SD

Diameter 10" 1 1/4"

Bearing N74 E N82 W

Distance 18 32

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

(Signature)

(Date)

(Title)

58

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 147N R. 27W Mer. 576

Form 574-0—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

L-21

Chippewa NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY



T. 147N R. 27W 5th Mer.
1/4 Corner common to Sections

_____, _____, 14, and 12

Corner consists of a Iron Pipe (not) in place
 State condition _____

Dimensions above ground 1" 28 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.
 CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species J.P. J.P.
 Diameter 10" 11"
 Bearing N47 1/2 E N82 W
 Distance 18 3 1/2

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

(Signature)

(Date)

(Title)

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

L-21

Chippewa NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 147N, R. 27W 5 1/2 Mer.
 1/4 Corner common to Sections

14, and 13
 Corner consists of a Iron Pipe (not) in place



State condition just erected

Dimensions above ground 1' - 28" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species JP JP

Diameter 10" 11"

Bearing N47 1/4 E N82 0 W

Distance 18 32

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

(Signature)


(Date)

(Title)

58

(Make sketch of topography near Corner)

T. 142 N. R. 27 W. Mer. 5-7h



Metal Location Poster is on a

tree inches diameter, on the

side of

from which this Corner bears

chains distant.

Give any further facts which will aid in finding this

Corner again.