

U. S. Department of Agriculture

FOREST SERVICE

V-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 177N R. 21W 5th Mer.

Corner common to Sections

35, and 36

Corner consists of a stone (not) in place



State condition new

Dimensions above ground 1' - 28" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species NO SP

Diameter 6

Bearing N 52 E

Distance 26 110

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

(Signature)


(Date)

(Title)

96

Metal Location Poster is on a tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_ side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. H. R. Mer. 576

U. S. Department of Agriculture

FOREST SERVICE

Chipewi

v 23 R

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147<sup>th</sup> R. 77<sup>th</sup> Mer.

Corner common to Sections 25, 26, and 36



Corner consists of a iron pipe (not) in place  
State condition new

Dimensions above ground 1' - 78" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species NO BT

Diameter 5 6

Bearing N54E OE

Distance 20 40

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

39.8 ft. 31.02 ft.

(Signature)

(Date)

(Title)

26.40

66.40

39.60

6.60

60

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 141N R. 27W 5th Mer.

U. S. Department of Agriculture

FOREST SERVICE

V-23

Philippine NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

Corner common to Sections

25 and 30

Corner consists of a I.P. in place



State condition

Dimensions above ground 1" 27 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound is located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species NP, JP

Diameter

Bearing N51E, N0E

Distance 60, 47

Do you believe this to be a genuine Land Office Corner?

If not, why?

(Signature)

(Date)

(Title)

96

Handwritten notes on ruled lines, including the number "172" and other illegible text.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. T. W. R. 2712  
Mer.