

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

N-23

CORNERS OF THE PUBLIC SURVEY

T. 107N R. 27W 5th Mer.

14

Corner common to Sections

13, and 29

Corner consists of a Iron Pipe in place



State condition

Dimensions above ground 1-28 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of ~~_____~~ is located ~~_____~~

Pits are located ~~_____~~

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Tam Tam

Diameter 5"

Bearing N 30 1/2 E S 84 1/2 E

Distance 50 62

Do you believe this to be a genuine Land Office Corner?

If not, why?

[Handwritten signature]

(Signature)

(Date)

(Title)

56

Faint, illegible text at the top of the page, possibly bleed-through from the reverse side.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

N-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

1/4 Corner common to Sections 13, and 24

Corner consists of a Iron Pipe (act) in place



State condition just erected

Dimensions above ground 1' - 28" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Iron Iron

Diameter 5" 5"

Bearing N30° E S54° E

Distance 50 62

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

(Signature)

(Date)

(Title)

56

U. S. Department of Agriculture
FOREST SERVICE

P
N-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147A R. 27W 5th Mer.

1/4 Corner common to Sections



13, and 24

Corner consists of a Iron Pipe (not) in place

State condition just erected

Dimensions above ground 1' - 28" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Tom. Tom.

Diameter 5" 5"

Bearing N30 1/2 E S84 1/2 E

Distance 56 62

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

(Signature)

(Date)

(Title)

56

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 147N R. 27W S 7A Mer.