

U. S. Department of Agriculture
FOREST SERVICE

523 P

Chipewau NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N. R. 27 W. 5th Mer.

1/4 Corner common to Sections
12, and 13

Corner consists of a Iron pipe (not) in place



State condition Just sketched

Dimensions above ground 1" - 2 1/2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species T37 T37

Diameter 3" 3"

Bearing N58°E S61°W

Distance 26 19


Do you believe this to be a genuine Land Office Corner?
If not, why? Yes

(Signature)

1936
(Date)

(Title)

Metal Location Poster is on a
 tree inches diameter, on the
 side of
 from which this Corner bears
 chains distant.
 Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)

Mer.

T. 147N R. 27W

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST J-23

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 27W 5th - Mer.

74

Corner common to Sections

12, and 13

Corner consists of Iron (not) in place



State condition

Dimensions above ground 1 - 26 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound is located is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Tam Tam

Diameter 3 1/2

Bearing N 50° E 50 pds

Distance 76 19

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

(Signature)

(Date)

(Title)

51

Faint, illegible text at the top of the page, possibly bleed-through from the reverse side.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

5-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

1/4 Corner common to Sections
12, and 13

Corner consists of a iron pipe in place



State condition just erected

Dimensions above ground 1" - 26 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species 2m 2m

Diameter 3" 3"

Bearing N58°45' E 66 1/4 W

Distance 26 19'

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____


(Signature)

1936
(Date)

(Title)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. LAZAR R. 270 Mer.