

U. S. Department of Agriculture

FOREST SERVICE

A-25

Superior NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *147N* R. *R2W* S. *5th* Mer.

Section Corner common to Sections *30, 31, 1, and 6*



Corner consists of a *Concrete Mark* (not) in place
State condition *Just Erecuted*

Dimensions above ground *7" - 24"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *J. Q. J. Q. J. Q.*
 Diameter *5 1/2" 5 1/2" 5 1/2" 5 1/2"*
 Bearing *N15W S45W S51W N60W*
 Distance *44 43 29 37*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

(Signature)

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

A-25

CORNERS OF THE PUBLIC SURVEY

T. 147 N. R. 27 W. 24 Mar.

Section Corner common to Sections
30, 31, 1, and 36

Corner consists of a log in place
State condition just cut

Dimensions above ground 7 - 24 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

R 27 W	R 26 W
S 30	S 31
S 4	S 6
T 147 N	T 148 N

Front of corner on NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and
fill blanks below, giving bearings from Corner to Trees and
Distances in Links.

T 149	T 149	T 147	T 148
S 31	S 30	S 31	S 36
BT	BT	BT	BT

Species	<u>SP</u>	<u>SE</u>	<u>WP</u>	<u>SB</u>
Diameter	<u> </u>	<u> </u>	<u> </u>	<u> </u>
Bearing	<u> </u>	<u> </u>	<u> </u>	<u> </u>
Distance	<u> </u>	<u> </u>	<u> </u>	<u> </u>

Do you believe this to be a natural Land Office Corner?
If not, why? Yes

Geological Survey

Geological Survey

CORNERS OF THE PUBLIC SURVEY

Corner again

Give any further facts which will aid in finding this


chain distant

from which this corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Scale shown of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

A25
R

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

Section Corner common to Sections
36, 31, 1, and 6

Corner consists of a Concret Mon. (not) in place



State condition just erected

Dimensions above ground 7"-24" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

7149
A26
531

7147
A36
566

7147
A27
5.1

7148
A27
536

B.t.

B.t.

B.t.

B.t.

Species 1 P. 1 P. 1 P. 1 P.

Diameter 8 7 5 7

Bearing N113°E S45°E S54°W N60°W

Distance 44 43 29 37

Do you believe this to be a genuine Land Office Corner yes

If not, why? _____


(Signature)

(Date)

(Title)

Metal Location Poster is on a _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)