

Form 874-0—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

A to E-1

Chippewa NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY



T. 142N R. R27W 511- Mer.
Meadow Corner common to Sections
 _____, _____, 1, and 6

Corner consists of a Iron Pipe (new) in place
 State condition Just Erected

Dimensions above ground 1 - 27 inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION



DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species W Oak Poplar
 Diameter 10" 10"
 Bearing S70°E N19°W
 Distance 96 70

Do you believe this to be a genuine Land Office Corner? Yes
 If not, why? _____

(Signature)

(Date)

(Title)

11310

U.S. DEPARTMENT OF AGRICULTURE

FOREST SERVICE

REPORT MADE FOR THE FOREST SERVICE

CORNER OF THE PUBLIC SURVEY

Corner again. Give any further facts which will aid in finding this

Chain distant

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

<p>Sketch of topography near corner</p>	<p>Sec.</p>	<p>Sketch of topography near corner</p>	<p>Sec.</p>
<p>Sketch of topography near corner</p>	<p>Sec.</p>	<p>Sketch of topography near corner</p>	<p>Sec.</p>

(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

Mounds Corner common to Sections
_____, _____, and 6

Corner consists of a Iron Pipe (not) in place



State condition just erected

Dimensions above ground 1 - 27 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species W. Oak Poplar

Diameter 10" 10"

Bearing S-70°E N-19 3/4°W

Distance .96 .70

Do you believe this to be a genuine Land Office Corner? Yes
If not, why? _____

G.H.D.
(Signature)

1936
(Date)

(Title)

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

A to E-1

Chipewee NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. *117N* R. *27W* 5th Mer.

Trunk Corner common to Sections
 _____, _____, and _____

Corner consists of a *Iron Pipe* (not) in place



State condition *Just Elected*

Dimensions above ground *1 - 27* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *W.O. Paper*

Diameter *10"* *10"*

Bearing *S-70°E* *N-19 3/4°W*

Distance *.96* *.70*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

G. L. O.
 (Signature)

1936
 (Date)

(Title)

D, E-1 8-7394

316

(Make sketch of topography near Corner)

T. 44N R. 27W S. 11E Mer.

	Sec. 6	Sec. 1	Sec.
	R 27W	R 28W	

Metal Location Poster is on a

tree inches diameter, on the

side of

from which this Corner bears

chains distant.

Give any further facts which will aid in finding this

Corner again.

MC

#E 2 ROW
1)

N SHOTE

LOWE Pigeons

