

U. S. Department of Agriculture
FOREST SERVICE

589

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEYT. 147 R. 27 5th Mer.

Manner Corner common to Sections
-----, -----, 8, and 17

Corner consists of a 6" squared post (not) in place
State condition Scribed, very good

Dimensions above ground 48 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and
fill blanks below, giving bearings from Corner to Trees and
Distances in Links.

T. 147 N. R. 27 W.			
S. W			

Species W.P.Diameter 2 1/2"Bearing S. 29 W.Distance 391 lks.Do you believe this to be a genuine Land Office Corner? Yes

If not, why? -----

5/2/35
(Date)

J. P. Honola
(Signature)
Tech. Foreman
(Title)

COMMENT ON THE FINDING

Corner again.
About 4 chs. E. of six mile
Lake Firway

Give any further facts which will aid in finding this


39 lbs. chains distant.

from which this Corner bears N. 29 E

side of the sec. line

tree 20 inches diameter, on the south.

Metal Location Poster is on a W. Pino



(Make sketch of topography near Corner)

T. 147 R. 27 Mer. 5th