

U. S. Department of Agriculture
FOREST SERVICE

P
R 16-17

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 27 W 5th Mer.
Meander Corner common to Sections

22, and 27

Corner consists of a brass cap on pipe in place
State condition good

Dimensions above ground 18 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

SE			

Species Oak

Diameter 6"

Bearing S 85° E

Distance 1.75 chs.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

June 1, 1935 (Date)
J. J. Donohue (Signature)
J. J. Donohue (Title)

