

U. S. Department of Agriculture

FOREST SERVICE

ST-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 177N R. 27W 5th Mer.

M.C.

Corner common to Sections

24, and 30

Corner consists of a I P (not) in place


State condition J E

Dimensions above ground 1 - 08 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N

W

S

E

NW

SW


SE

NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Aspen*

Diameter 8" 8"

Bearing N90°22'W N15°25'E

Distance 3.51 3.66

Do you believe this to be a genuine Land Office Corner?

If not, why?

(Signature)

(Date)

(Title)

Metal Location Poster is on a tree _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.

	Sec.		Sec.
	Sec. 2	Sec. 5	
	427	428	

(Make sketch of topography near Corner)

T. L. H. R. 220 Mer.